


热处理检验报告

Heat Treatment Inspection Certificate

热处理状态/	调质	炉次号/	JT2025-10-25	
Heat Treatment Status:		Furnace No.		
零件图号/	198P020N00	数量/	1 件	
Part Drawing No.		Quantity:		
零件名称/	Gear	材料/	42CrMo4	
Part Name:		Material.		
硬度检查/Hardness Inspection				
零件编号 Part No.	硬度 / Hardness			
	要求/Required: HB285-310			
	304	305	308	
	301	303	302	
备注/Remark:		判定意见		合格
		Inspection Result		Accepted
检验员/Inspector:刘浩		日期/Date:2025. 8. 28		

一号炉过程曲线



一号炉过程曲线

