




MESHING REPORT

啮合报告

ITEM NO.序号	PART & REV. NO. 零件号	MOUNTAING DISTANCE 安装距	ACTUAL BACKLASH 实际隙	SCETCH DRAWING草图
1	TB3026 & TB3029	L1=30.00	0.10	/
2		L2=47.00		

TESTING PICTURES拓印图



INSPECTOR 质检员	Pan	RESULT 检验结果	OK	DATE日期	2026.1
---------------	-----	-------------	----	--------	--------