




MESHING REPORT

啮合报告

ITEM NO.序号	PART & REV. NO. 零件号	CENTER DISTANCE 安装距	CENTER HEIGHT 中 心高	ACTUAL BACKLASH 实际隙	SCETCH DRAWING
1	s5904337	46.25	24	C=0.21	
TESTING PICTURES拓印图					
INSPECTOR 质检 员	Zheng	RESULT 检验结果	ok	DATE日期	2025/5/24